


Universal Group®






The Universal Group Corp 1025 Thomas Busch Memorial Highway  Pennsauken, New Jersey 08110

1120 Eden Road, Suite 100  Arlington, Texas 76001


Hendrickson HAULMAAX



NJ Phone: (800) 225-1845  (856) 488-1800  NJ Fax: (800) 360-9636

 TX Phone: (800) 637-4422

Hendrickson HAULMAAX



<p>H-22186-000 Transverse Rod Frame Bracket</p>  <p>Flagg E336-50 Dayton Parts 338-181 Automann M919</p>	<p>SLN- 3/4 3/4"- 16 UNF Locknut</p> 	<p>H-34013-087L Bar Pin Kit, no shims</p>  <p>Flagg BP87 Dayton Parts 334-830 Automann BP198</p>
<p>H-34013-088L Bar Pin Kit with shims</p>  <p>Flagg BP88 Dayton Parts 334-831 Automann BP200</p>	<p>H-47691-000 ULTRA ROD Straddle Bushing</p>  <p>Flagg HS44 Dayton Parts 321-223 Automann TRB6185</p>	<p>H-50130-000 Bar Pin Shim 0.19 / 0.19</p>  <p>Flagg HS41 Dayton Parts 334-879 Automann MHS106</p>
<p>H-57878-003 Rebound Strap</p>  <p>Flagg HS91 Dayton Parts 334-1623 Automann MHS206</p>	<p>H-57974-046 Aux Spring Contact Plate Fastener</p> 	<p>H-59384-000 Aux Spring Mounting Bracket</p>  <p>Dayton Parts 338-1934 Automann MHS227</p>
<p>H-60304-000 Upper Shock Bracket</p> 	<p>H-60314-000 Auxiliary Spring</p>  <p>Automann MHS225</p>	<p>H-60613-000 Rebound Support Angle</p> 
<p>H-60680-004 Shock Absorber Assembly</p> 	<p>H-60680-005 Shock Absorber Assembly</p> 	<p>H-60791-000 Auxiliary Spring Shim - 0.25"</p>  <p>Flagg HS132 Dayton Parts 334-1728 Automann A109</p>

H-62350-615

2 Piece Torque Rod



Automann TMRN1051

H-64178-003- H-64178-004

Service Shock Kit 16.5 -17.5/18.5



H-64179-004

Auxiliary Spring Service Kit,
One Side



Flagg HS99
Dayton Parts 334-1720
Automann MHS225K

H-64179-028

Rebound Strap Service Kit,
One Side



Dayton Parts 334-1722
Automann MHS231

H-64179-037

Tie-bar Bolster Spring Service Kit



Flagg HS130
Dayton Parts 334-1845
Automann MLC5

H-64595-003

Frame Bracket



H-64636-001

Frame Bracket



H-64642-000

HAULMAAX 400



H-64643-000

HAULMAAX 460



H-64846-001

Equalizing Beam Assembly
54", with Shock Bracket



Automann MHS6481

H-64890-000

Aux Spring Contact Plate Kit



Flagg HS101
Dayton Parts 334-1719
Automann MHS448
Replaced 64179-005

H-66610-000

ULTRA ROD Two-Piece Torque Rod Kit



Automann TMRN610

H-66661-000

ULTRA ROD Two-Piece Torque Rod Kit



Automann TMRN661