


Universal Group®






The Universal Group Corp 1025 Thomas Busch Memorial Highway  Pennsauken, New Jersey 08110

1120 Eden Road, Suite 100  Arlington, Texas 76001

Hendrickson MAXAIR / AL405 Air Suspension








NJ Phone: (800) 225-1845  (856) 488-1800  NJ Fax: (800) 360-9636





 TX Phone: (800) 637-4422



Hendrickson

MAXAIR / AL405 Air Suspension
Mack "Twisted Sister"
Tandem Axle Air Suspension



50-433-OE	50-435-OE	H-22186-000	H-49947-000
LH Main Support Member (H-58691-000)	RH Main Support Member (H-58768-000)	Torque Rod Frame Bracket 	Spherical Washer 
		(Flagg E336-50, Dayton Parts 338-181)	(Flagg HS123, Dayton Parts 334-1695)

H-57241-006	H-58648-000	HT-58701-001 HT-58702-001	H-58772-001
Shock Absorber 	QUIK-ALIGN Pivot Bushing 	LH Lower Shock Bracket RH Lower Shock Bracket 	Frame Hanger 
(Flagg HS107, Dayton Parts 341-57241-6)	(Flagg HS102, Dayton Parts 321-387)	(Dayton Parts 338-1926, 338-1927)	(Dayton Parts 338-1924)

H-58776-000 U-Bolt Spacer Tuber 	H-59580-006 H-64237-003 H-59582-005 H-59582-006 H-59582-008	Spring Seat Front (4.5°) Spring Seat Front (7.5°) Spring Seat Front (12.0°) Spring Seat Front (12.5°) Spring Seat Front (13.5°)	
--	--	---	--

H-58786-002 Air Spring Assembly 	H-60661-000 QUIK-ALIGN Concentric Base (in kit H-60683-001) 	H-60662-000 QUIK ALIGN Eccentric Base (in kit H-60683-001) 
	(Flagg HS125, Dayton Parts 334-1694)	(Flagg HS126, Dayton Parts 334-1693)

Kit 60683-001	H-65084-000
Kit Contains 6 pcs. H-60661-000 2 pcs. H-60662-000 4 pcs. H-58705-003 4 pcs. H-60266-000 8 pcs. H-22962-034 4 pcs. H-58648-000	Service Kit, QUIK ALIGN w/bushing  (Dayton Parts 334-1690)
	Top Pad  (Dayton Parts 338-1925)

Universal Group®



www.theuniversalgroup.com