


Universal Group®





The Universal Group Corp 1025 Thomas Busch Memorial Highway  Pennsauken, New Jersey 08110


1120 Eden Road, Suite 100  Arlington, Texas 76001

Mack Camelback Rear Suspension

4" Spring, 3 1/2" Bronze Center




NJ Phone: (800) 225-1845  (856) 488-1800  NJ Fax: (800) 360-9636

 TX Phone: (800) 637-4422

Mack 4" Spring, 3 1/2" Bronze Center

Replacement Parts




SM-3.5 Kit W/B

(with bushings)



SM-3.5 Kit

(without bushings)



DN - 1/4	H-66610-000	H-66690-000 (27" - 35") H-66691-000 (to 27")
<p>Hi-Nut</p> <p>Dayton Parts DN125 Flagg DN8 Automann HN114</p>	<p>Ultra Rod Two Piece Torque Rod</p> <p>Dayton Parts 345-610 Flagg UR610 Automann TMRN610</p>	<p>Ultra Rod Two Piece Torque Rod</p> <p>H-66690-000 Dayton Parts 345-690 Flagg UR690 Automann TMRN690</p> <p>H-66691-000 Dayton Parts 345-691 Flagg UR691 Automann TMRN691</p>

PAD 36B	SUB 12014	PAD-365A	SUB 12006	PAD-370	SUB 12010
<p>Lower Mack Pad</p> <p>Dayton Parts 325-110 Flagg MP2 Automann ABP2</p>	<p>Upper Mack Pad</p> <p>Dayton Parts 325-112 Flagg MP1 Automann ABP1</p>	<p>Upper Mack Pad</p> <p>Dayton Parts 325-113 Flagg MP4 Automann ABP4</p>	<p>Upper Mack Pad</p> <p>Dayton Parts 325-113 Flagg MP4 Automann ABP4</p>	<p>Upper Mack Pad</p> <p>Dayton Parts 325-113 Flagg MP4 Automann ABP4</p>	<p>Upper Mack Pad</p> <p>Dayton Parts 325-113 Flagg MP4 Automann ABP4</p>


RCM-001	SE-316	SE-411 SE-412
<p>Mack 3.5 Trunion</p> <p>Dayton Parts 338-702 Flagg E435-62 Automann M1116</p>	<p>Spacer Block</p> <p>Dayton Parts 338-729 Flagg E316-62 Automann M878</p>	<p>Insulator Box</p> <p>SE-411 Dayton Parts 338-728 Flagg E411-62 Automann M1068</p> <p>SE-412 Dayton Parts 338-746 Flagg E412-62 Automann M1070</p>

SE-456	SM-3.5 Kit W/Bushings	SM-3.5 Kit
<p>Mack 3.5 Trunion</p> <p>Dayton Parts 334-468 Flagg E456-62 Automann M1158</p>	<p>Mack Trunion 3.5 Kit with Bushings</p> <p>2 pcs SM-001 1 pc SM-002 1 pc SM-004 1 pc SM-006 1 pc SM-011 2 pcs TBM-255</p>	<p>Mack Trunion 3.5 Kit</p> <p>2 pcs SM-001 1 pc SM-002 1 pc SM-004 1 pc SM-006 1 pc SM-011</p>

SLN-1.0	SM-001	SM-002
<p>Lock Nut</p> <p>Dayton Parts SSN-107 Flagg SN-107</p>	<p>Bronze Thrust Washer</p> <p>Dayton Parts 334-443 Flagg MCK1 Automann MX302</p>	<p>Steel Thrust Washer</p> <p>Dayton Parts 334-444 Flagg MCK2 Automann MX303</p>



SM-004	SM-006	SM-011
<p>Trunnion Lock Ring</p>  <p>Dayton Parts 334-442 Flagg MCK4 Automann MX305</p>	<p>Trunnion Seal</p>  <p>Dayton Parts 334-445 Flagg MCK6 Automann MX301</p>	<p>Trunnion Collar Nut</p>  <p>Dayton Parts 334-441 Flagg E677-62</p>

SMTB-3.5	SMR-N x 4 x Length	SMQ-N x 4 x Length
<p>Trunnion Bar</p>  <p>Dayton Parts 334-466 Automann MB1</p>	<p>Mack Round U-Bolt</p> <p>Lengths</p> <ul style="list-style-type: none"> 13.5 14.5 15.5 16.5 17.5 18.5 19.5 	<p>Mack Square U-Bolt</p> <p>Lengths</p> <ul style="list-style-type: none"> 13.5 14.5 15.5 16.5 17.5 18.5 

TBM-255	UBW - 1 ¼	
<p>Bronze Trunnion Bushing</p>  <p>Dayton Parts 322-114 Flagg MIB255 Automann MX300</p>	<p>U-Bolt Washer</p>  <p>Dayton Parts SUW125 Flagg UBW90</p>	

Any reference to OEM names, part numbers, model numbers or description is for identification only and does not indicate that it is an OEM part.